Paragon II Release 4.8.2

Release Notes—October 15, 2012

Overview

Paragon II Release 4.8.2 provides several enhancements and maintenance items – particularly the release of high definition DDC adapters.

Updated Firmware

Version 4.8.2 of Paragon II provides firmware updates for several of the platform's components. New firmware updates include:

Firmware	Version Number
P2-UMT	3EN
P2-EUST	3F7
P2CIM-AUSB	0F6
P2CIM-AUSB-C	1A9
P2CIM-APS2	3C2
P2CIM-APS2DUAL	2A6
Paragon Manager	2.0.4.5.2

Please refer to the Compatibility Matrix for the complete list of all current Paragon II component firmware.

Updated User Documents

The following Paragon II user documents have been updated:

Document	Version Number
Paragon II User Guide	PII-1A-v4.8-E

Obtaining Updates

New release 4.8.2 firmware and documentation can be accessed at Raritan's Paragon II support page: http://www.raritan.com/support/Paragon-II/.   Please download the compatibility matrix from this same location and review it before proceeding with your installation of release 4.8.2.

Enhancements

New DDC adapters support for high definition resolutions

Two DDC adapters are released to support widescreen resolutions: 1920*1080 with 16:9 ratio and 1920*1200 with 16:10 ratio on 21'' and 23'' LCD displays.

Part number	Description	US List Price
DDC-1080P	DDC adapter for 1920x1080 resolution	US$10
DDC-1920	DDC adapter for 1920x1200 resolution	US$10

Maintenance

The following maintenance issues have been addressed in release 4.8.2 (Note – ID numbers in this section are reference numbers internal to Raritan.)

ID	Summary
43727	Support SW2-USB and SW4-USB as Front-End Switches to P2-EUST
43853	UKVMSP's ZCIMS cannot working with Paragon II
43910	UKVMSTD is not working as a local access feature since upgrade to 4.8.0
44287	Mouse jumping when User port 5 and User port 7 use at the same time
43775	Mouse jumping when port 6 and 8 are used at the same time
43996	Server released automatically when use "Previous CH key"
45183	Wrong key input on P2CIM APS2 DUAL
45155	admin logout message onscreen while admin still is on same target
45462	P2-EUST no contact issue.
44287	mouse jumping when User port 5 and User port 7 use at the same time