

Release Notes for MasterConsole Z

May 25th, 2006

Welcome! This document contains the Release Notes for the MasterConsole Z.

Effective:	Immediately
Applicability:	<ul style="list-style-type: none">• MZUST• MZCIM-PS2, MZCIM-USB, MZCIM-SUN
Release Status:	General Availability on May 25th, 2006 .
Expiration date of content:	This document will be obsolete when the next generally available release is posted on the Raritan web-site. Check Website (http://www.raritan.com/support) for updated versions of MasterConsole Z software update(s), which will contain updated release notes as well.
Release Package Details:	New MasterConsole Z units will come with the latest firmware on it or can be downloaded from the Raritan web site. The external web site will include a zipped file that contains the latest release notes, firmware and upgrade application.

Release Content:

I. For this release, listed below are known issues that are being worked on for future MasterConsole Z firmware release.

Description
Random: The screen may go black when MZUST is running with MZCIM (rare occurrence).
Random: When the user operates their KB & MS in the channel, or while switching channels, the MZCIM chain may rebuild (rare occurrence).
Random: Master MZCIM may display an extra character at the end of its name (rare occurrence).

Obtaining Additional Assistance

Should you have any questions about the MasterConsole IP, please call Raritan Technical Support at 1-800-724-8090.