

CommandCenter® Secure Gateway Release 3.0.2

Please review the Release Notes for important release information. Please consult the Quick Setup Guide, Deployment Guide, and User Guide for product information on setup instructions, implementation, and operations. CommandCenter Secure Gateway documents can be located both on the enclosed document CD and under Product Documentation at www.raritan.com/support/

I. Compatibility Matrix

It is important that you upgrade any listed Raritan products to the specified versions indicated in order to have CommandCenter Secure Gateway work effectively.

CommandCenter Secure Gateway Release 3.0.2 firmware info:

| RARITAN PRODUCTS | FIRMWARE VERSION | SHIPS WITH |
|---|------------------|---|
| CommandCenter Secure Gateway: CC-SG E1 CC-SG V1 CC-SG G1 | 3.0.2 | Raritan Remote Client (RRC) 4.6.2 Multi Platform Client (MPC) 4.6.2 Raritan Console (RC) 2.7.19 |

Firmware version of CC-SG can be located under Help→About Raritan CommandCenter.

Firmware versions of all Raritan devices can be verified by running an Asset Management Report in CommandCenter Secure Gateway under Reports.

CommandCenter Secure Gateway Release 3.0.2 has been tested against the following Raritan products with its' corresponding supported firmware versions and tested against supported client applications specified.

| RARITAN PRODUCTS SUPPORTED | | SUPPORTED FIRMWARE VERSIONS | |
|----------------------------|--|-----------------------------|--|
| Product Name/Model | Part # | Current | Previous |
| Dominion KX *1 | DKX101 | 1.0.1 | 1.0.0 |
| Dominion KX *1 | DKX116, DKX216, DKX232, DKX416, DKX432 | 1.4.7*2 | 1.4.6*2, 1.4.5*2, 1.4.2*2, 1.4.1*2, 1.4.0, 1.3.0 |
| Dominion KX *1 | DKX132, DKX464 | 1.4.7*2 | 1.4.6*2, 1.4.5*2, 1.4.2*2, 1.4.1*2, 1.4.0 |
| Dominion KSX | DKSX440, DKSX880 | 3.23 | 3.22, 3.21 |
| Dominion SX | DSX16, DSX32 | 2.5.7 | 2.5.6.5, 2.5.6, 2.4.6 |
| Dominion SX | DSX4, DSX8, DSXA16, DSXA32, DSXA48 | 2.5.7 | 2.5.6.5, 2.5.6, 2.4.5 |
| IP-Reach M1/M2 and | IPR-M1, IPR-M2, | 3.23 | 3.21 |

| | | | |
|-----------------------------------|------------------------------|--------------|--------------|
| TR-series (formerly TeleReach) | IPR-TR364 | | |
| Paragon II System Controller | P2-SC | 1.2.0 | N/A |
| CommandCenter NOC | CC-NOC 250, 2500 M/N/S | 5.4.0 | 5.3.0 |
| Power Strips | PCR8, PCR12, PCR18, PCR20 | N/A | N/A |

*¹ for best results, Raritan strongly recommends that KX devices be re-booted before the firmware upgrade is applied. You can reboot the KX devices directly from CommandCenter Secure Gateway by scheduling a reboot prior to upgrade for all KX devices using the Task Manager feature (under the Setup menu).

*² when adding a device running this firmware version from CC-SG you shall see the warning message: "The firmware version on this device is not officially supported by CommandCenter Secure Gateway." You should respond to prompt "Do you wish to proceed?" by clicking on "Yes."

Also, new versions of MPC and RRC may be available for download on the web at <http://www.raritan.com/support/firmwareupgrades/commandcentersecuregateway>

| OTHER PRODUCTS SUPPORTED | | SUPPORTED FIRMWARE VERSIONS | | SUPPORTED CLIENT APPLICATIONS |
|--------------------------|--|-----------------------------|----------|-------------------------------|
| Product Name/Model | | Current | Previous | |
| iLO | | 1.82 | 1.64 | N/A |
| RILOE | | 2.52 | 2.52 | N/A |
| RILOEII | | 1.16 | 1.13 | N/A |

| CLIENT PLATFORMS | SUPPORTED BROWSERS | SUN JRE SUPPORT |
|------------------|--|---------------------------|
| Win 2000 | Internet Explorer 6.0, Netscape 8.0 / 8.1, Mozilla 1.7.12, Firefox 1.5.0.1 | 1.4.2_02 to 1.4.2_11, 1.5 |
| Win XP | Internet Explorer 6.0, Netscape 8.0 / 8.1, Mozilla 1.7.12, Firefox 1.5.0.1 | 1.4.2_02 to 1.4.2_11, 1.5 |
| RedHat9 | Mozilla 1.7.12, Firefox 1.5.0.1 | 1.4.2_02 to 1.4.2_11, 1.5 |
| SUSE 9.2 | Mozilla 1.7.12, Firefox 1.5.0.1 | 1.4.2_02 to 1.4.2_11, 1.5 |
| Solaris 9, 10 | Netscape 7.1, Mozilla 1.7.12, Firefox 1.5.0.1 | 1.4.2_02 to 1.4.2_11, 1.5 |
| MacOS 10.4 | Firefox 1.5.0.1 | 1.4.2_01 to 1.4.2_05, 1.5 |

Sun JRE can be found at <http://java.sun.com/j2se/>

II. Firmware Upgrades

Raritan provides new firmware upgrade and related documentation on the internet. This information is available for download and review on our website, on the Firmware Upgrades page under Support: http://www.raritan.com/support/sup_upgrades.aspx